

## REPORT ABOUT THE MOTOR VEHICLES ACCIDENTS

1	Name of Police station	Basamba Police Station Date 02/01/2026
2	CR NO/Tar no /Sde No	02/2026 Us 106(1), 285, 125(A)125(B), 324(4) BNS 2023
3	Date time and place of the accident	Date 01/01/2026 at 03. 30 PM At Near Basamba Corner Hotel Hingoli Bypass road
4	Name of injured/Deceased	Deceased – 1) Pransingh Visana Ahirwar R/O Gramredy Himatpur Tq Khaniyadan Dist Shivpur
5	Name of hospital to which he/she was removed	
6	Number of vehicle and type of the vehicle	1) Truck No UP 94 AT 4149 2) Truck No RJ 09 JD 7930
7	Name and address of the driver of vehicle with particulars or Driving license of the side driver and the address of the issuing authority of the side driving license the no of badge in case of public service vehicle and the address of the issuing authority of the side badge	1) Truck No UP 94 AT 4149 2) Truck No RJ 09 JD 7930
8	Name of address of owner of the vehicle as it stands date of accident	----
9	Name and address of the insurance campony with whom the vehicle was insured and the divisional office the side insurance campony	----
10	No of insurance policy/ insurance certificate and the date of validity of insurance policy/ insurance certificate	----
11	Action taken if any and the result there of	As above
		Police Inspector Basamba Police Station